

Tue 10/5/2021 12:29 AM

Campus Power Outage Condition – Research Advisory



Dear colleagues,

On October 4, 2021, at 8:37 p.m., UCI experienced a campuswide power outage, which affected many buildings. Power was restored to the campus at 11:01 p.m. A brief walkthrough of campus buildings was conducted.

In the morning, when researchers arrive in their labs, they should verify that critical systems including fume hoods, biosafety cabinets, and ultra-low temperature freezers have restarted automatically. If they have not, then researchers should take steps to manually restart systems and freezers.

Take caution when restarting electrical systems and please report any safety-related concerns to the Facilities Management Service Desk at 949-824-5444, or through the [With U - For U](#) mobile app (available for [iOS](#) and [Android devices](#)).

Sincerely,

John Sterritt

Executive Director
Environmental Health and Safety

Bruce Morgan

Associate Vice Chancellor for Research Administration
Office of Research